

To: Larry Teig[larry.teig@odayequipment.com]
From: Galbraith, Erin
Sent: Thur 3/21/2013 5:55:32 PM
Subject: RE: Meleen's Sport Center-Onamia, Mn

Larry,

Thank you for getting back to me on this, I'm glad to know we are getting closer to a resolution.

Erin Galbraith
Underground Storage Tanks Section
Land and Chemicals Division
U.S. EPA Region 5
77 W. Jackson Blvd. (LR-8J)
Chicago, IL 60604
312-886-6879
312-697-2659 (fax)

From: Larry Teig [larry.teig@odayequipment.com]
Sent: Thursday, March 21, 2013 12:10 PM
To: Galbraith, Erin
Cc: Al Peach
Subject: Meleen's Sport Center-Onamia, Mn

While on site on Friday, March 15th, I spoke with Tech support at OPW and found out something I did not know-the predecessor EECO 1500 by EMCO Wheaton to this OPW 1500, if the programming had an option for tank leak testing that said "continuous", it meant continuous segmented leak detection; Not so with the OPW 1500-continuous only means it does continuous leak testing whether it is doing "SLD" or continuous static leak testing(which is what their system was doing). The only way to tell if it has continuous sld testing or continuous static testing is by getting the software version off of the main board chips and asking OPW tech support. When Paul was informed of this he sent a check in with me, so we could order the correct software. As soon as we get it, I will be going to the site, installing the software and then reprogramming the tank monitor, so that it performs the correct leak testing.

Larry Teig

Service Technician

O'Day Equipment

Brainerd, Mn Office

larry.teig@odayequipment.com